


Repair Kit SP/BP/RP "SN" 1500 - Part No. RK-0550



1

EL-0020 Diaphragm w/hole -1500 psig, Buna QTY 3




2

EL-0200 O-Ring, -010, Buna, 3/8 x 1/4 x 1/16 QTY 2



3

EL-0210 O-Ring,-012, Buna, 1/2 x 3/8 x 1/16 QTY 3




4

EL-0220 O-Ring,-014, Buna, 5/8 x 1/2 x 1/16 QTY 2




5

EL-0230 O-Ring,-109, Buna, 1/2 x 5/16 x 3/32 QTY 1




6

EL-0235 O-Ring,-112, Buna, 11/16 x 1/2 x 3/32 QTY 2




7

EL-0237 O-Ring,-116, Buna, 15/16 x 3/4 x 3/32 QTY 1




8

EL-0240 O-Ring,-147, Buna, 2-7/8 x 2-11/16 x 3/32 QTY 4




9

PD-0494 SN Lng Piston + SEAT



10

Mobilith SHC 220 Standard VRG Lubricant



11

FN-0109
10-32 x 1/2
FHMS 18-8 SS;
#93082A520
with Thread Locker
QTY 4